9424/

## **Subsurface Sewage Treatment System Maintenance Permit**

· · · · ·	Property/Owner Information  Permit #: 200783394 (pumping code)  omplete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing naintenance activities and remain on-site for the duration of the maintenance activity.	
	roperty Address: 1548/ 209 th ST. N Stillwater MN 55073 Street Address City State Zip roperty Owner Name: Patrick J. Phippen	
	Maintenance Performed   Tanks Pumped: OR   □ Emergency Liquid Level of Tank:in Sludge Level:in   □ Home Sale Scum Level:in   □ High-level alarm Scum Level:in   ☑ Routine/Maintenance Sludge+Scum/Liquid Levelx100=%Sludge & Scum   □ Compliance Inspection Tanks must be Pumped if 25% or greater   □ Other: Tanks must be Pumped if 25% or greater	
A	Maintenance Information  Were all covers securely replaced? Yes □No If No, Explain: □ Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1: □Yes ☒No Verification Method Used: Û S W O INSP. Gallons Removed: 1500  Leaking Out: □Yes ☒No Leaking In: □Yes ☒No Cover Damaged: □Yes ☒No  Tank #2: □Yes ☒No Verification Method Used: □ Gallons Removed: 1500  Leaking Out: □Yes ☒No Leaking In: □Yes ☒No Cover Damaged: □Yes ☒No  Tank #3: □Yes □ No Verification Method Used: □ Gallons Removed: □ Leaking Out: □Yes □ No Cover Damaged: □Yes □ No  Tank #4: □Yes □ No Verification Method Used: □ Gallons Removed: □ Leaking Out: □Yes □ No Leaking In: □Yes □ No Cover Damaged: □Yes □ No  Pump Tank: ☒Yes □ No Verification Method Used: Û S W O Cover Damaged: □Yes ☒No  Pump Tank: ☒Yes □ No Verification Method Used: Û S W O Cover Damaged: □Yes ☒No  Waste Disposal Method: □Treatment plant □ Land Apply: Location □ Other remarks or Concerns: □	
	Maintainer Information Maintainer Name: Sherco Construction, Inc. Maintainer Address: 79 North Lake Street Forest Lake, MN 55025 Phone Number: (651) 462-1817 License Number: L1675 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly	



supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.