## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 043397537064	
Complete in its entirety to constitute a valid r maintenance activities and remain on-site for	naintenance normit. This name it
Date of Maintenance: 9-24-24	Property ID #:
Property Address: 1020 Pen Liela Street Address	Ave N Stillwufer MN 55082 City State Zip
Property Owner Name: Kurt we	ber
Maintenance Performed	
Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank: in Sludge Level: in  Scum Level: in
☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge+Scum/Liquid Levelx100=%Sludge & Scur  Tanks must be Pumped if 25% or greater
Were all covers securely replaced? ☐ Yes[ Is the tank designed as a leaky? Ex. Seepa	tenance Hole Other (enter authorization code)  □ No If No, Explain: <u>Cook Not acess manke</u> uge pit, cesspool drywell leaching pit
Leaking Out: Yes No Leaking In Yes □	Used: VISUCUI Gallons Removed: 500
Tank #2:□ Yes □ No Verification Method	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes  Tank #3: ☐ Yes ☐ No Verification Method  Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	Used: Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method	Jsed: Gallons Removed:
Pump Tank: ☐ Yes ☐ No Verification Meth	od Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Waste Disposal Method: ☐ Treatment plar Other remarks or Concerns:	□ No Cover Damaged: □Yes □ No  It □ Land Apply: Location <u>ST Paul met</u> Council
Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Address: P.O. Box 354 Afton, MN Phone Number: 651-439-4847	License Number: L4251
I hereby certify as a State of Minnesota certified SSTS M supervised others in the performance of this job.  Maintenance activities must be reported to the supervised of the	laintainer that I personally conducted the work and made the observations, or directly

Washington County