Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	etion Permit #: 1014 w 36979
Complete in its entirety to constitute a valid maintenance activities and remain on-site for	maintananae nama't Ti'
Date of Maintenance: 9-13-24	Property ID #:
Property Address: 05/9 10+ Street Address	St No lake Elma MM 5504/2 City State Zip
Property Owner Name: JEFF Senske	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scur Tanks must be Pumped if 25% or greater
Were all covers securely replaced? ☐ Yes Is the tank designed as a leaky? Ex. Seep Tank #1: ☐ Yes ☐ No Verification Method	ontenance HoleOther (enter authorization code) S□No If No, Explain: Dage pit, cesspool drywell leaching pit Subsect: Viscol Gallons Removed: 1500
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes	□ No Cover Damaged: □ Yes □ No Used: □ Gallons Removed:
Tank #3: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes Tank #4: ☐ Yes ☐ No Verification Method	Used: Gallons Removed: S □ No Cover Damaged:□Yes□No Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Pump Tank: ☐ Yes ☐ No Verification Met Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ Waste Disposal Method: ☐ Treatment place.	hod Used: Gallons Removed:
Other remarks or Concerns: Home ou	uner declined manhole use
Maintainer Information Maintainer Name: Pinky's Sewer Service In Maintainer Address: P.O. Box 354 Afton, M Phone Number: 651-439-4847 I hereby certify as a State of Minnesota certified SSTS	c. Maintainer Signature Jame 1
supervised others in the performance of this job. Maintenance activities must be reported	

Washington County