Subsurface Sewage Treatment System Maintenance Permit

| Property/Owner Information | Permit #: 60596736437 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. | |
| Date of Maintenance: 09/09/Je20 | Property ID #: |
| Property Address: Street Address | Muchal Rel NO STIMULATO MN 55087 |
| Property Owner Name: Hard a McConn | |
| Maintenance Performed | |
| Tanks Pumped: ☐ Emergency ☐ Home Sale | tanks Not pumped) |
| ☐ High-level alarm ☐ Routine/Maintenance | Liquid Level of Tank:in Sludge Level:in Scum Level:in |
| ☐ Compliance Inspection ☐ Repair | Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater |
| ☐ Other: Maintenance Information | on |
| were all covers securely replaced? Yes | ntenance Hole Other (enter authorization code) |
| Is the tank designed as a leaky? Ex. Seep | age pit resspool drywell loaching pit |
| Tank #1: ☐ Yes ☑ No Verification Method | Used: ViSual Gallons Ramavada 1 = 6 |
| reaking out. Trestaino reaking int likes | NO Cover Damaged:□Yes No |
| Tank #2: ☐ Yes ☐ No Verification Method | Used: Gallons Removed: |
| Leaking Out: Yes No Leaking In: Yes | □ No Cover Damaged: □ Yes □ No |
| Tank #3: ☐ Yes ☐ No Verification Method | Used: Gallons Removed: |
| Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes | □ No Cover Damaged: □Yes □ No |
| Tank #4: ☐Yes ☐ No Verification Method | Used: Gallons Removed: |
| Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes | □ No Cover Damaged:□Yes□No |
| Pump Tank: ☐ Yes ☐ No Verification MetI | nod Used: Gallons Removed: |
| Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes | □ No Cover Damaged:□Yes□No |
| Waste Disposal Method: Treatment pla | nt 🗆 Land Apply: Location |
| Other remarks or Concerns: S 15+em | ecid for manhore |
| Maintainer Information | |
| Maintainer Name: Pinky's Sewer Service Inc | Maintainer Ciny |
| Maintainer Address: P.O. Box 354 Afton, MI | Maintainer Signature: |
| Phone Number: 651-439-4847 License Number: L4251 | |
| I hereby certify as a State of Minnesota certified SSTS Maintain and Land U | |
| supervised others in the performance of this job. Maintenance activities must be reported to the Department within 20.1. | |

Washington County