Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: X1406237966	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 10/30/24	* Property ID #:
	ave Hugo MN 55038 ° State Zip
Property Owner Name: Chuck Hags	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scun Tanks must be Pumped if 25% or greater
Maintenance Information	
	enance Hole Other (enter authorization code)
	No If No, Explain:
Is the tank designed as a leaky? Ex. Seepa	
	Jsed: Visual Gallons Removed: 1500
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐	
	Jsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes [
	Jsed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes [
Tank #4: ☐Yes ☐ No Verification Method U	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Pump Tank: ☐ Yes ☐ No Verification Meth	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Waste Disposal Method: ☐ Treatment plan	
Other remarks or Concerns:	
THE RESERVE OF THE PARTY OF THE	
Maintainer Information	111-28
Maintainer Address: 17638 Lynn St. Alf. 5	
Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216	
I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly	
supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days	

