Subsurface Sewage Treatment System Maintenance Permit

Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. Date of Maintenance:	Property/Owner Information Permit #: <u>c8784e37981</u> Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Property Address: 3408 5044 Street Address Street Address Street Address City State Zip Maintenance Performed Tanks Pumped: Tanks Pum			
Maintenance Performed	Date of Maintenance: 11/1/24	Property ID #:	
Maintenance Performed	Property Address: 13408 150+h St Street Address	City State Zip	
Tanks Pumped: Emergency Home Sale High-level alarm Froutine/Maintenance Compliance Inspection Repair Cother: In Sludge Level:	Property Owner Name: Tim + Becky Severson		
Emergency Home Sale High-level alarm Souther Maintenance Compliance Inspection Repair Tanks must be Pumped if 25% or greater Sludge & Scum Tanks must be Pumped if 25% or greater Tan	Maintenance Performed		
Maintenance Information Access used to remove septage:	☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair	Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/in Sludge+Scum/in x100=%Sludge & Scum	
Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: Yes No Verification Method Used: Visual Gallons Removed: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #2: Yes No Verification Method Used: Visual Gallons Removed: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #3: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Tank #4: Yes No Verification Method Used: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Gallons Removed: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns: Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature: Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216		n	
Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082	Were all covers securely replaced? Yes Is the tank designed as a leaky? Ex. Seepa Tank #1: Yes No Verification Method Leaking Out: Yes No Verification Method Leaking Out: Yes No Verification Method Leaking Out: Yes No Leaking In: Yes Tank #3: Yes No Verification Method Leaking Out: Yes No Verification Method	□No If No, Explain: age pit, cesspool drywell leaching pit Used: V:sucl Gallons Removed: ISBO SNo Cover Damaged:□Yes No Used: V:sucl Gallons Removed: 500 ENO Cover Damaged:□Yes No Used: Gallons Removed: TSO SNO Cover Damaged:□Yes□No SNO Cover Damaged:□Yes□No SNO Cover Damaged:□Yes□No SNO Cover Damaged:□Yes□No SNO Cover Damaged:□Yes□No	
Maintainer Name: Olson's Sewer Service Inc. Maintainer Signature: Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, as directly.	Maintainer Information	和某些特殊的原理。	
	Maintainer Name: Olson's Sewer Service In- Maintainer Address: 17638 Lyons St. NE Ford Phone Number: 651-464-2082 License	est Lake, MN 55025 Number: L216	

Washington County

Maintenance activities must be reported to the Department within 90 days.