Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: v2262f37980	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: $U/U/24$ Property ID #:	
Property Address: 167 Bichner LN Street Address	Mahtored Mu 55115 City State Zip
Property Owner Name: Doug Chapman	
Maintenance Performed	
Tanks Pumped: Emergency Home Sale High-level alarm Compliance Inspection Repair Other: Maintenance Information	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Test No If No, Explain: Pump through Pipe due to excessive Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit depth and seepage tank #1: Pres No Verification Method Used: Gallons Removed: 1000	
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Tank #2:ဩYes □ No Verification Method Used: Visual Gallons Removed: 500 Leaking Out:□Yes□No Leaking In:□Yes□No Cover Damaged:□Yes□No	
Tank #3₺₫Yes □ No Verification Method Used: U`Sua ☐ Gallons Removed: 1000 ☐ Leaking Out: □ Yes □ No Cover Damaged: □ Yes □ No	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No	
Pump Tank: ☐ Yes ☑ No Verification Method Used: U(sua/ Gallons Removed: 300 Leaking Out: ☐ Yes ☑ No Cover Damaged: ☐ Yes ☑ No	
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location	
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082	
Maintenance activities must be reported to the Department within 90 days.	

Washington County