

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	for Maintenance: _	Routine	8 1500	
Property Address: 8570 Jewel Ave N, Stillwater,	, MN P	roperty Owner's Na	ame: Pearl Lemieux	- Augustania
Municipality: ZIP: 5508	2 Property Iden	ntification Number:	h	
Maintenance Permit No: Ma				
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
☑ Tank(s) Pumped		ank in		
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?			evel X 100 nks must be pumped	
\square Yes \square No (if no provide measurements)	- % Stadge & Sca	ra	iks mase be pampea	ii 25% or greater
1. Access used to remove septage: Maintenan	ce Hole 🛛 Other (e	enter authorization co	ode)	
2. Were all covers securely replaced? Yes				
		eatment or pump	tank below the ope	rating depth or
Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura	lly unsound main	tenance hole cove	rs? <u>No-couldn't</u>	conf <u>irm precast via</u>
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	─────────────────────────────────────			
Septic/Holding rank #1	- Yes I No			
38 38 1840			yes No ough inspection pipe.	
Septic/Holding Tank #2	Some answers unl		ugh inspection pipe.	
Septic/Holding Tank #2 Pretreatment Tank	Some answers unl	known. Pumped thro	ugh inspection pipe.	
	Some answers unl	known. Pumped thro	ugh inspection pipe.	
Pretreatment Tank Pump Tank	Yes No Yes No Yes No	known. Pumped thro	Yes No	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed?	Some answers unl Yes No Yes No Yes No Yes No	known. Pumped thro	Yes No Yes No	an l
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 1250 gal Tank #2	Some answers und Yes No Yes No Yes No gal Pretreatment	known. Pumped thro	yes No Yes No Yes No Pes No	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 1250 gal Tank #2 5. Other information: List any troubleshooting,	Some answers und Yes No Yes No Yes No gal Pretreatment minor repairs con	known. Pumped thro	yes No Yes No Yes No Pes No	
Pretreatment Tank Pump Tank 4. How many gallons of septage were removed? Tank #1 1250 gal Tank #2	Some answers und Yes No Yes No Yes No gal Pretreatment minor repairs con	known. Pumped thro	yes No Yes No Yes No Pes No	

Schlomka Services, LLC 17560 Northfield Blvd Hastings, MN 55033

License# 2989 P: 651-459-3718