Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Inform	nation	ermit #: 70489 k37650
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: WASDODU	Property ID #:	
Property Address: 10150 Kerry (Street Address	Hugo City	MN SS038 State Zip
Property Address: 10150 Kerry (4N Hugo MN 55038) Street Address City State Zip Property Owner Name: Brad Boucher		
Maintenance Performed		
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Liquid Level of Tank:	uid Levelx100=%Sludge & Scui
Maintenance Informat	ion	
Access used to remove septage: M Were all covers securely replaced? Is the tank designed as a leaky? Ex. Se Tank #1: \(\) Yes \(\) No Verification Meth	es□No If No, Explain:epage pit, cesspool drywell le	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No		
Tank #2: ☐ Yes ☐ No Verification Meth	od Used:	Gallons Removed:
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No		
Tank #3: ☐ Yes ☐ No Verification Meth Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	od Used: Yes □ No Cover Damaged:□	Gallons Removed: Yes□No
Tank #4: ☐Yes ☐ No Verification Meth		
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ \	Yes□No Cover Damaged:□	Yes□No
Pump Tank: Yes No Verification Method Used: Leaking Out: Yes No Cover Damaged: Yes No Waste Disposal Method: Treatment plant Land Apply: Location Other remarks or Concerns:		
Maintainer Information Maintainer Name: Smilie's Sewer Servi Maintainer Address: P.O. Box 100 Scar Phone Number: 651-433-3935 Lice	N ice Maintain ndia, MN 55073 nse Number: _{L2428}	er Signature: All Vallet et de la vallet de

Washington County

Maintenance activities must be reported to the Department within 90 days.