Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informa	tion Permit #: 773 67 i37947
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 11/11/26 24	Property ID #:
Property Address: 5750 Hytro Street Address	Property ID#: !! Ave Luke Elmo MN 55042 City State Zip
Property Owner Name: Don - Lynn Kloek	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Koutine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scur Tanks must be Pumped if 25% or greater
Were all covers securely replaced? Tyes	tenance Hole Other (enter authorization code) □No If No, Explain:
Is the tank designed as a leaky? Ex. Seep	
	Used: Gallons Removed: Soo
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes	No Cover Damaged: Yes No
Tank #2: ☐ Yes ☐ No Verification Method	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Tank #3: ☐ Yes ☐ No Verification Method	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Tank #4: ☐ Yes ☐ No Verification Method	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Pump Tank: ☐ Yes ☐ No Verification Met	nod Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	□ No Cover Damaged: □Yes □ No
Waste Disposal Method: Treatment pla	nt □ Land Apply: Location
Other remarks or Concerns:	
I hereby certify as a State of Minnesota certified SSTS	Maintainer Signature: A. MN 55073 Number: L2428 Maintainer that I personally conducted the work and made the observations, or directly
supervised others in the performance of this job.	# 17 \$2000 to 1

Washington County

Maintenance activities must be reported to the Department within 90 days.