## Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information	on Permit #: d 9799 \ 37977
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 1/-8-24 Property ID #:	
Property Address: 16332 Harros	City State Zip
Property Owner Name: Susan Kersten	
Maintenance Performed	
☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection	iludge and Scum Measured: (must be completed if tanks NOT pumped) iquid Level of Tank:in Sludge Level:in cum Level:in ludge+Scum/Liquid Levelx100=%Sludge & Scum anks must be Pumped if 25% or greater
Were all covers securely replaced ☑Yes□N Is the tank designed as a leaky? Ex. Seepage	
Tank #1: ☐Yes ☑ No Verification Method Us  Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑ Yes ☐ Yes	ed: Gallons Removed:/500
Tank #2:□Yes Ano Verification Method Us  Leaking Out:□Yes Ano Leaking In: □ Yes \	ed: Gallons Removed: foo o No Cover Damaged:□Yes⊠No
Tank #3: ☐ Yes ☐ No Verification Method Us Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	ed: Gallons Removed: No Cover Damaged: Yes No
Tank #4: ☐ Yes ☐ No Verification Method Us Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	Control of the Contro
Pump Tank: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Waste Disposal Method: Treatment plant □ Land Apply: Location	
	ntainer that I personally conducted the work and made the observations, or directly

