Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: 5\(\varphi\) 175a37978
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 11/11/24 Property ID #:
Property Address: 19549 Maning Trail Marine Mu 55047 ' Street Address City State Zip
Property Owner Name: Peter & Nancy Berven
Maintenance Performed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in
Maintenance Information Access used to remove septage: X Maintenance Hole Other (enter authorization code) Were all covers securely replaced? A Yes _ No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: A Yes _ No Verification Method Used: Visual Gallons Removed: 375 Leaking Out: _ Yes _ No Leaking In _ Yes _ No Cover Damaged: _ Yes _ No Tank #2: _ Yes _ No Verification Method Used: Gallons Removed: Leaking Out: _ Yes _ No Leaking In: _ Yes _ No Cover Damaged: _ Yes _ No
Tank #3:□Yes □ No Verification Method Used: Leaking Out:□Yes□No Leaking In:□Yes□No Cover Damaged:□Yes□No
Tank #4: Yes No Verification Method Used: Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes No Pump Tank: Yes No Verification Method Used: Gallons Removed: Looking Out: Yes No Verification Method Used:
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: A Treatment plant ☐ Land Apply: Location
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082

