

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. Date of Maintenance: 277/b Reason for Maintenance: 29 Maintenance						
DICTIM.						
Property Address: 21656 Manyles Tr. (VProperty Owner's Name: Sasan Mon 1						
Municipality:	udia zip:550	7 Property Ider	ntification Number:			
Maintenance Permit No	15423p4406 A	Naintainer Name an	d License No.Sm	iliès Sewers	Service 242	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks N	(OT pumped)	
Tank(s) Pumped		Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to rem	nove septage: Maintena	nce Hole 🗌 Other (6	enter authorization cod	de)		
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
		1				
	Septic/Holding Tank #1	☐ Yes ♠No	☐ Yes ①No	☐ Yes ☐ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
	S 20 80 80	V-10000 10 00000 00 €0000 00000	•	•		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
4. How many gallons	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 1250	Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank		
Tank #1 1250	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank		
Tank #1 1250	Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ? gal Pretreatment	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tank ga	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Pump Tank		