

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t	o constitute a vai	id maintenance per	mit. This permit must be complete
prior to perfor	ming maintenance activitie	es and remain on-	site for the duratio	n of the maintenance activity.
Date of Maintenance:	9-28-16 Reason f	or Maintenance: _	Regular	Maint.
Property Address: <u>Z</u>	0370 Ostvum Auc	. N P	roperty Owner's Na	me: Dan Vennemitz
Municipality: Mar	ne ZIP: 5504	7 Property Iden	tification Number:	
Maintenance Permit N	0:5299664410 M	aintainer Name an	d License No.Sm	ilies Sewer Service 248
Maintena	nce Performed	Tank Meas	urement (must be d	completed if tanks NOT pumped)
☑ Tank(s) Pumped		Liquid Level of Tank in		
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in		
Do tanks need to I		Sludge + Scum / Liquid Level X 100		
11 William Value (1997)	no provide measurements)	= % Sludge & Scu	ım Tanl	ks must be pumped if 25% or greater
4. Assess used to som	neve centage: V Maintenan	co Holo Other (e	enter authorization cod	de)
 Access used to remove septage: ✓ Maintenance Hole				
	Tank	Leaking Out	Leaking In	Cover Damage
	Tank Septic/Holding Tank #1	Leaking Out ☐ Yes ☑ No		Cover Damage ☐ Yes ☒ No
				☐ Yes ☒ No
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes ☒ No	☐ Yes ☒ No
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes 🌠 No	☐ Yes ☒ No	☐ Yes ☒ No
4. How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No
The second secon	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No	☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☐ No ☐ Yes ☒No	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No
Tank #1 / 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed? gal Tank #2	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☒ No	☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☐No ☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☒No	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No
Tank #1 / 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed? gal Tank #2	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☒ No	☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☐No ☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☒No	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No ☐ Yes ☒ No ☐ Pump Tank ☐ ☒ ☐ gal
Tank #1 / 1000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed? gal Tank #2	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☒ No	☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☐No ☐ Yes ☒No ☐ Yes ☒No ☐ Yes ☒No	☐ Yes ☒ No ☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☒ No ☐ Yes ☒ No ☐ Pump Tank ☐ ☒ ☐ gal