Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: DOIS A 38274
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.
Date of Maintenance: 11-15-24 Property ID #:
Property Address: C524 70th St wash the State Zip
Property Owner Name:
Maintenance Performed
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other: Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in
Maintenance Information Access used to remove septage Maintenance Hole Other (enter authorization code) Were all covers securely replaced yes _ No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1, Yes _ No Verification Method Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In ☐ Yes ☐ No Cover Damaged ☐ Yes ☐ No Tank #2: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ Gallon
Leaking Out: ☐ Yes ☐ Wes ☐ Wes ☐ Cover Damaged: ☐ Yes ☐ No Tank #3: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ Gallons Removed: ☐ Gallons Removed: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No
Pump Tank: ☐ Yes ☐ No Verification Method Used:
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216 I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Washington County

Maintenance activities must be reported to the Department within 90 days.