## **Subsurface Sewage Treatment System Maintenance Permit**

Property/Owner Information	Permit #: <u>65603K37581</u>
Complete in its entirety to constitute a valid maintenance activities and remain on-site fo	maintenance permit. This permit must be completed prior to performing or the duration of the maintenance activity.
Date of Maintenance: 11-13-24	Property ID #:
Property Address: 1407(50) Street Address	City State Zip
Property Owner Name:	Bastigens
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:in Sludge Level:in  Scum Level:in  Sludge+Scum/Liquid Levelx100=%Sludge & Scun  Tanks must be Pumped if 25% or greater
Maintenance Information	on San San San San San San San San San Sa
	ntenance Hole Other (enter authorization code)
Were all covers securely replaced AYYes	
Is the tank designed as a leaky? Ex. Seep	
Tank #1: ☐Yes ►No Verification Method	Used: Gallons Removed:/occ
Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes	
	Used: Gallons Removed:_/cow
Leaking Out: ☐ Yes ☑ No Leaking In: ☐ Yes	
	Used: Gallons Removed:
Leaking Out: ☐ Yes ØNo Leaking In: ☐ Yes	
	Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Pump Tank: ☐ Yes ☐ No Verification Met	:hod Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	
Waste Disposal Method: Treatment pla	ant 🗆 Land Apply: Location
Other remarks or Concerns:	
Maintainer Information Maintainer Name: Olson's Sewer Service In Maintainer Address: 17638 Lyons St. NE For Phone Number: 651-464-2082 License	

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

