Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: P4678T38275	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
Date of Maintenance: 11-19-24	Property ID #:
Property Address: 14/97 240th S	otate zip
Property Owner Name: Se Szczepanski	
Maintenance Performed	
☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater
Maintenance Information	
	nance Hole Other (enter authorization code) No If No, Explain: e pit, cesspool drywell leaching pit
Tank #1:□Yes IIHNo Verification Method U	sed: Gallons Removed:_/050
Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑	No Cover Damaged: ☐ Yes \(\sigma\) No
Tank #2:☐ Yes Ø No Verification Method U	sed: Gallons Removed:_/050
Leaking Out: ☐ Yes ☑ No Leaking In: ☐ Yes ☑	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	sed: Gallons Removed:
Tank #4: ☐Yes ☐ No Verification Method U	sed: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Pump Tank: Yes No Verification Metho	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Waste Disposal Method: Treatment plant Other remarks or Concerns:	Land Apply: Location
Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Fores Phone Number: 651-464-2082 License N	Maintainer Signature: t Lake, MN 55025 umber: L216 intainer that I personally conducted the work and made the observations, or directly



Maintenance activities must be reported to the Department within 90 days.