Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: F2445K38279	
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.	
	Property ID #:
Property Address: Street Address	owhere forestlake MN 55925 City State Zip
Property Owner Name:	
Maintenance Performed	国民和民国的 是1000年 1000年
Were all covers securely replaced? Exes Is the tank designed as a leaky? Ex. Seep Tank #1: Yes No Verification Method Leaking Out: Yes No Leaking In Yes Tank #2: Yes No Verification Method Leaking Out: Yes No Leaking In: Yes	Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum Tanks must be Pumped if 25% or greater Tanks must be Pumped if 25% or greater Other (enter authorization code) No If No, Explain:age pit, cesspool drywell leaching pit Used: Gallons Removed: No Cover Damaged: Yes No Used: Gallons Removed:
Tank #3: ☐ Yes ☐ No Verification Method Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	Used: Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Method	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes	□ No Cover Damaged: □ Yes □ No
Pump Tank: A es A No Verification Met Leaking Out: Yes No Leaking In: Yes Waste Disposal Method Teatment pla Other remarks or Concerns:	□ No Cover Damaged: □Yes □ No
Maintainer Information	
Maintainer Name: Olson's Sewer Service Ir Maintainer Address: 17638 Lyons St. NE For Phone Number: 651-464-2082 License	rest Lake, MN 55025 Number: L216
supervised others in the performance of this job. Maintenance activities must be reported	Maintainer that I personally conducted the work and made the observations, or directly I to the Department within 90 days.

