

Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information

Permit #: 28983V36602

Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 11-4-24 Property ID #: _____Property Address: 20363 OLINDA TR N Marine on St Croix MN 55047
Street Address City State ZipProperty Owner Name: Jesse Boudreau

Maintenance Performed

Tanks Pumped:

Emergency

Home Sale

High-level alarm

Routine/Maintenance

Compliance Inspection

Repair

Other:

OR

Sludge and Scum Measured: (must be completed if tanks NOT pumped)

Liquid Level of Tank: _____ in Sludge Level: _____ in

Scum Level: _____ in

Sludge+Scum/ _____ Liquid Level _____ x100= _____ %Sludge & Scum

Tanks must be Pumped if 25% or greater

Maintenance Information

Access used to remove septage: Maintenance Hole _____ Other (enter authorization code) _____Were all covers securely replaced? Yes No If No, Explain: _____

Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit

Tank #1: Yes No Verification Method Used: Visual Gallons Removed: 1,000Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes NoTank #2: Yes No Verification Method Used: Visual Gallons Removed: 1,000Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes NoN/A Tank #3: Yes No Verification Method Used: _____ Gallons Removed: _____Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes NoN/A Tank #4: Yes No Verification Method Used: _____ Gallons Removed: _____Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes NoPump Tank: Yes No Verification Method Used: Visual Gallons Removed: 250Leaking Out: Yes No Leaking In: Yes No Cover Damaged: Yes NoWaste Disposal Method: Treatment plant Land Apply: Location 29052 DIMAGGIO ST NE, North Branch MN

Other remarks or Concerns: _____

Maintainer Information

Maintainer Name: Ross' Sewer Service, Inc.

Maintainer Signature: [Signature]

Maintainer Address: 9288 County Road 5 NE North Branch, MN 55056

Phone Number: 651-674-4349 License Number: L 3448

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.