Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #:
Date of Maintenance: 11 - 70 - 2024 Property ID #:
Property Address: 21133 Penrose Ave. Scandia MN Street Address City State Zip Property Owner Name: Tames Williams Guy Hovnburg
Tapita > Community
Maintenance Performed Tanks Pumped: or □ Emergency Liquid Level of Tank:in □ High-level alarm Scum Level:in □ Routine/Maintenance Scum Level:in □ Compliance Inspection Sludge+Scum/Liquid Levelx100=%Sludge & Scum □ Repair Tanks must be Pumped if 25% or greater
Were all covers securely replaced? Yes \ No If No, Explain: \ Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: \ Yes \ No Verification Method Used: \ Usu \ Openity \ Order \
Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location Other remarks or Concerns:
Maintainer Information Maintainer Name: Sherco Construction, Inc. Maintainer Address: 79 North Lake Street Forest Lake, MN 55025 Phone Number: (651) 462-1817 License Number: 11675

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

License Number: L1675

Maintenance activities must be reported to the Department within 90 days.

