Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informa	Permit #: 1 6 399, 3 1916
maintenance activities and remain on-site fo	maintenance permit. This permit must be completed prior to performing or the duration of the maintenance activity.
Date of Maintenance: 11 08 2024	Property ID #:
Property Address: 1390 Jan Street Address Property Owner Name: Ed Sup	laca Grant MN 55082 City State Zip
Street Address	City State Zip
☐ Emergency ☐ Home Sale ☐ High-level alarm ⚠ Routine/Maintenance ☐ Compliance Inspection	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scum
□ Repair □ Other:	Tanks must be Pumped if 25% or greater
Maintenance Information Access used to remove septage: Ma Were all covers securely replaced?	aintenance Hole Other (enter authorization code)
Is the tank designed as a leaky? Ex. See	epage pit, cesspool drywell leaching pit
Tank #1: ☐ Yes ☑ No Verification Metho Leaking Out: ☐ Yes ☑ No Leaking In ☐ Ye	od Used: Gallons Removed: \SSOC
	od Used: Gallons Removed:
	od Used: Gallons Removed:
Tank #4: ☐ Yes ☐ No Verification Metho	od Used: Gallons Removed:
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Y	
Pump Tank: Yes No Verification M	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Y	
Other remarks or Concerns:	plant □ Land Apply: Location <u>Netro</u>
Maintainer Information Maintainer Name: Smilie's Sewer Servi Maintainer Address: P.O. Box 100 Scar Phone Number: 651-433-3935 Lice	ce Maintainer Signature:

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.



T: (651) 430-6655 | F: (651) 430-6730