## Subsurface Sewage Treatment System Maintenance Permit

| Complete in its entirety to constitute a valid resist   |
|---|
| Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.  |
| Date of Maintenance: 12/11/24  Property ID #:   |
| Property Address: 1849le July Ave Forest Lake MN 55015 Street Address City State Zip  |
| Property Owner Name: Tim + Lisa Picha   |
| Maintenance Performed   |
| Tanks Pumped:  ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair   Sludge and Scum Measured: (must be completed if tanks NOT pumped)  Liquid Level of Tank:   |
| Other:  Maintenance Information  Access used to remove septage:   Maintenance Hole   Other (enter authorization code)  Were all covers securely replaced?   Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit  Tank #1:   Yes No Verification Method Used:   Leaking Out:   Yes No Leaking In Tyes The Course Removed:   Tank #1 Course Removed:   Gallons Removed:   Tank #1 Course Removed:   Maintenance Hole   Other (enter authorization code)  Other (enter authorization code)  Gallons Removed:   Gallons Removed:   Tank #1:   Yes No Leaking In Tyes The Course Removed:   Other (enter authorization code)   |
| Tank #2:□ Yes No Verification Method Used: Uisual Gallons Removed: 1000  Leaking Out:□ Yes No Leaking In:□ Yes No Cover Damaged:□ Yes No.   |
| Tank #3: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ Gallons Removed: ☐ Gallons Removed: ☐ Cover Damaged: ☐ Yes ☐ No Tank #4: ☐ Yes ☐ No Verification Method Used: ☐ Gallons Removed: ☐ Gall |
| Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No  Pump Tank: ☐ Yes ☐ No Verification Mathed User Leaking Out: ☐ Yes ☐ No  |
| Leaking Out:  |
| Maintainer Information Maintainer Name: Olson's Sewer Service Inc. Maintainer Address: 17638 Lyons St. NE Forest Lake, MN 55025 Phone Number: 651-464-2082 License Number: L216 hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job. Maintenance activities must be reported to the Department within 90 days.  |

Washington County