Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Informa	tion Permit #: M0427C38547
Complete in its entirety to constitute a valid n maintenance activities and remain on-site for	Naintonanao normit This
Date of Maintenance: 12/18/2024	Property ID.#:
Property Address: 12950 NORFLL Street Address	AVE N STILLWATER MN 55082 City State Zip
Property Owner Name: KEUIN CONNERS	
Maintenance Performed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank: in Sludge Level: ir Scum Level: in Sludge+Scum/ Liquid Level x100=%Sludge & Scur Tanks must be Pumped if 25% or greater
Is the tank designed as a leaky? Ex. Seepag	nance Hole Other (enter authorization code) No If No, Explain: The pit, cesspool drywell leaching pit
Tank #1: ☐Yes ☐ No Verification Method U	sed: Gallons Removed: 1000
Leaking Out: ☐ Yes No Leaking In ☐ Yes 🛛	No Cover Damaged: ☐ Yes No
Leaking Out: Yes No Leaking In: Tyes	sed: Gallons Removed:_880
Tank #3:□Yes □ No Verification Method U Leaking Out:□Yes□No Leaking In:□Yes □	sod.
Tank #4:□Yes □ No Verification Method U	
Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐	
Pump Tank: ☐ Yes ☐ No Verification Metho	
Leaking Out:□Yes□No Leaking In:□ Yes□	
Waste Disposal Method: Treatment plant Other remarks or Concerns:	□ Land Apply: Location FRIOLE , MN
	Maintainer Signature: Lake, MN 55025 umber: L216 ntainer that I personally conducted the work and made the observations, or directly
Maintenance activities must be reported to the Department within 90 days.	

