

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety to	constitute a vali	d maintenance per	mit. This permit n	nust be complete
prior to perform	ning maintenance activitie	s and remain on-	site for the duration	n of the maintenar	nce activity.
Date of Maintenance:	10-3-16 Reason fo	or Maintenance: _	Cleaning		
	250 190th St.			me: Gloria	Splinter
Municipality: Forest	Lake ZIP: 5502	S Property Iden	tification Number: _		
	: <u>+1146m4373</u> Ma				
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b	***	Sludge + Scum / Liquid Level X 100			
Andrew Programmer State Section 1	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
	nove septage: Maintenand		nter authorization coc	de)	
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	-
	of septage were removed?				
Tank #1 1,500	2 gal Tank #2	gal Pretreatmen	t tankga	l Pump Tank 3	<i>00</i> gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safet	y concerns, or oth	er concerns.
					-
6. Location of septage	e disposal:				