Subsurface Sewage Treatment System Maintenance Permit

Property/Owner Information Permit #: <u>d 9629h37357</u>		
Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.		
Date of Maintenance: 10-28-24		Property ID #:
Property Address: 14570 Old - Street Address	field	Rd. M. Marlne on St Croix M. M. 55047 City State Zip
Property Owner Name: Kevin kiesow		
Maintenance Perform	ed	
Tanks Pumped: ☐ Emergency ☐ Home Sale ☐ High-level alarm ☐ Routine/Maintenance ☐ Compliance Inspection ☐ Repair ☐ Other:	OR	Sludge and Scum Measured: (must be completed if tanks NOT pumped) Liquid Level of Tank:in Sludge Level:in Scum Level:in Sludge+Scum/Liquid Levelx100=%Sludge & Scu Tanks must be Pumped if 25% or greater
Maintenance Informa	tion	
Were all covers securely replaced? Is the tank designed as a leaky? Ex. S	Yes□ Seepag thod U	Jsed: U Sucul Gallons Removed: 1250
Tank #2:□ Yes □ No Verification Met	Jsed: Gallons Removed:	
Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No		
Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No		
Tank #4: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed:		
Leaking Out:□Yes□No Leaking In:□	Yes □	No Cover Damaged: ☐ Yes ☐ No
Waste Disposal Method: ☑ Treatment Other remarks or Concerns: しつ	t plant	t - Land Apply: Location - ST Paul met Council
Maintainer Information Maintainer Name: Pinky's Sewer Service Maintainer Address: P.O. Box 354 Aftor Phone Number: 651-439-4847 I hereby certify as a State of Minnesota certified supervised others in the performance of this job.	ce Inc. n, MN	
Maintenance activities must be reported to the Department with a continuous to the Department of the continuous to the c		

Washington County