

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be compl	eted in its entirety to	o constitute a valic	maintenance perr	nit. This permit m	ust be complete
prior to performing r	naintenance activitie	s and remain on-s	te for the duratior	of the maintenan	ce activity.
Date of Maintenance: _/0 - ?	Reason fo	or Maintenance:	Cleening		
Property Address: 5025	Northbrook	Blud Pro	perty Owner's Nan	ne: Melenie	Shockey
Municipality: Still- whe	ZIP: 550%	2 Property Ident	ification Number: _		
Maintenance Permit No:	Ma	aintainer Name and	License No. Smilie	e's Sewer Service/L2	2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Service as service N *		Sludge Level in Tank in Scum Level in Tank in			
☐ Sludge and scum measured Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
Yes \(\subseteq \text{No (if no provide measurements)} \)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove s Were all covers securely Is there evidence of tan evidence of damaged, 	replaced? Yes [k leakage from a sept	☐ No cic, holding, pretre	eatment or pump to	ank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
Septi	c/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ Mo	
Septi	c/Holding Tank #2	☐ Yes ☐ Mo	☐ Yes ☐No	☐ Yes ☐ No	
Pretr	eatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pum	p Tank	☐ Yes ☐ Ho	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of se	ptage were removed?	?			
Tank #1 1000 gal Tank #2 1.000 gal Pretreatment tank gal Pump Tank 400 gal					
Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal S. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
6. Location of septage disp	osal:				7