Subsurface Sewage Treatment System Maintenance Permit Property/Owner Information Permit #: 29499377 Complete in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. Date of Maintenance: Property ID #: Property Owner Name: Ron Ober muller Maintenance Performed Tanks Pumped: Sludge and Scum Measured: (must be completed if tanks NOT pumped) OR ☐ Emergency Liquid Level of Tank: _____in ☐ Home Sale ☐ High-level alarm Scum Level: in □ Routine/Maintenance Sludge+Scum/_____kSludge & Scum □ Compliance Inspection □ Repair Tanks must be Pumped if 25% or greater ☐ Other: Maintenance Information Access used to remove septage: ____ Maintenance Hole ____ Other (enter authorization code) + CWQCU Were all covers securely replaced? ☐Yes☐No If No, Explain: Is the tank designed as a leaky? Ex. Seepage pit, cesspool drywell leaching pit Tank #1: ☐ Yes ☐ No Verification Method Used: _ V FULLY Gallons Removed: \500 Leaking Out: ☐ Yes ☑ No Leaking In ☐ Yes ☑ No Cover Damaged: ☐ Yes ☑ No Tank #2:☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Tank #3: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Tank #4: ☐Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Pump Tank: ☐ Yes ☐ No Verification Method Used: Gallons Removed: Leaking Out: ☐ Yes ☐ No Leaking In: ☐ Yes ☐ No Cover Damaged: ☐ Yes ☐ No Waste Disposal Method: ☐ Treatment plant ☐ Land Apply: Location _ Net Colnell Other remarks or Concerns: Maintainer Information Maintainer Name: Pinky's Sewer Service Inc. Maintainer Signature:

Maintainer Address: P.O. Box 354 Afton, MN 55001

Phone Number: 651-439-4847 License Number: L4251

I hereby certify as a State of Minnesota certified SSTS Maintainer that I personally conducted the work and made the observations, or directly supervised others in the performance of this job.

Maintenance activities must be reported to the Department within 90 days.

