Pd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	to constitute a	alid maintenance	permit This permit mu	et he completed
1					
prior to perio	orming maintenance activi	nes and remain d	n-site for the dura	tion of the maintenance	e activity.
Date of Maintenance	: 10-13-16 Reason	for Maintenance:			
Property Address: \$635 170th ST Property Owner's Name: Steven Watz					watel
Municipality: Ha	80 ZIP: 550	Property Id	entification Number	•	_
	No: <u>0303254480</u> 1				
Mainten	ance Performed	Tank Me	surement must be	completed if tanks No	Fedniped) · ·
Tank(s) Pumped		Tank in		12	
☐ Sludge and scum	measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	um Tai	nks must be pumped if 2	5% or greater
1. Access used to re	move septage: Maintenar	nce Hole Other (enter authorization co	ode)	<i>,</i>
2. Were all covers se	curely replaced? X Yes	□No			(
	of tank leakage from a sep aged, cracked, or structura				ng depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes Ø No	☐ Yes ☑ No	☐ Yes ⊠No	
	Septic/Holding Tank #2	☐ Yes ⊠No	☐ Yes ♥No	☐ Yes ⊠No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes KNo	☐ Yes 风No	☐ Yes ØNo	
4. How many gallons	Pump Tank ————of septage were removed?	☐ Yes ⊠No	☐ Yes 风No	☐ Yes ENNO	
		,	and the second s		_ gal
Tank #1 1000	of septage were removed?	gal Pretreatment	tankga	l Pump Tank 383	-
Tank #1 1000	of septage were removed?	gal Pretreatment	tankga	l Pump Tank 383	-
Tank #1 1000	of septage were removed? gal Tank #2 (0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	gal Pretreatment	tankga	l Pump Tank 383	-