

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entire	ety to constitute a	valid maintenance	permit. This permit	must be completed
prior to per	forming maintenance acti	vities and remain o	on-site for the dur	ation of the maintena	nce activity.
Date of Maintenance	e: 10-7-16 Reas	on for Maintenance	: Ma Selli	10 home	
Property Address:	3099 Itasca	Averoph	Property Owner's	Name: DULF Di	anne Jumsun
Municipality:	ZIP:	Property Id	lentification Numbe	er:	
Maintenance Permit	No: 1406214472	Maintainer Name	and License No.	SST - #211	(
Lightee	alakes/représpient		Encerten Antico	te stom liteles (if limits)	Nicht sumpled)
Tank(s) Pumped		Liquid Level of	Tank in)	
Sludge and scum measured Sludge Level in Tank in Scum Level in Tank in					in
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (i	f no provide measurement	s) = % Sludge & So	cum Ta	anks must be pumped i	if 25% or greater
1. Access used to re	move septage: Mainter	nance Hole Other	enter authorization (code)	, ,
2. Were all covers s	ecurely replaced? Pes	i □ No			
	of tank leakage from a se aged, cracked, or structu				ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ØNo	☐ Yes ☐No	☐ Yes ੴNo	
	Septic/Holding Tank #2	☐ Yes ੴNo	☐ Yes 🕅 No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☑No	☐ Yes ☐No	☐ Yes ੴNo	
4. How many gallons	of septage were removed	i ?		~	
Tank #1 1560	gal Tank #2 1000	gal Pretreatment	tank 600 ga	al Pump Tank	gal
	: List any troubleshooting				concerns.
6. Location of septage	disposal: Metvo				