



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entiret	y to constitute a v	alid maintenance p	ermit. This permit mu	st be completed	
prior to perfe	orming maintenance activ	ities and remain o	n-site for the dura	tion of the maintenanc	e activity.	
Date of Maintenance	:_[1-3-16 Reason	n for Maintenance:	P.M.			
Property Address:	5101 Riverside A	ue	Property Owner's N	lame: Carely & Ielry	Patrin	
	ZIP:					
Maintenance Permit	No: 14968614853	Maintainer Name a	and License No. O	SSI - #2116		
√.÷ Asintek	tion Performed	Maria Sile	alpenent tions to	kenn present family are	recompany and	
Tank(s) Pumped		11	Tank in	e in man it die 👉 andere versteren der versteren der versteren de ver		
☐ Sludge and scum	measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	tum Tai	nks must be pumped if 2	25% or greater	
1. Access used to rea	move septage: Maintena	ance Hole 🗌 Other (enter authorization co	ode)	· · · · · · · · · · · · · · · · · · ·	
	ecurely replaced? Yes			4		
3. Is there evidence evidence of dame	of tank leakage from a se aged, cracked, or structur	ptic, holding, pret rally unsound mair	reatment or pump stenance hole cove	tank below the operati rs?	ing depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ❷No	☐ Yes ♥No	☐ Yes ☑No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☑No	☐ Yes ☑No	☐ Yes № No		
4 How many callons	of septage were removed	?				
4. How many gamens			120 V	1 2 1 222		
Tank #1 \500	gal Tank #2				gal	
Tank #1 \500	gal Tank #2					
Tank #1 \500						