

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety	to constitute a va	id maintenance pe	ermit. This permit m	ust be completed	
<u>prior</u> to perform	ning maintenance activit	ies and remain on	site for the durati	on of the maintenance	ce activity.	
Date of Maintenance:	8-74-14 Reason	for Maintenance: _	Routine			
Property Address: 63	11 Kismet Au	2 N F	roperty Owner's Na	ame: Raren	Bissonnett	
Municipality: Still	wester ZIP:530	Property Idea	ntification Number:			
	:d6408 m37100 1				wer Service/L1673	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers sect</li><li>3. Is there evidence of</li></ul>	ove septage:	□ No otic, holding, pretr	eatment or pump	tank below the opera	iting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
_	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons o	f septage were removed	?				
Tank #1 ) 750	gal Tank #2	gal Pretreatment	tankga	al Pump Tank	gal	
	List any troubleshooting uncler flouring			ty concerns, or other		
6. Location of septage	disposal:		Freedom production and the contract of the con			