7-20



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a valid maintenance	permit. This permit must be comp	oleted
<u>prior</u> to performing maintenance activiti	es and remain on-site for the dur	ation of the maintenance activity.	
Date of Maintenance: 7.27-16 Reason	for Maintenance: Routpue		
Property Address: 9390 75th St	Property Owner's	Name: Sally Anders	SON
Municipality: Still water ZIP550	Property Identification Number	er:	
Maintenance Permit No 37658 2-3581 M	aintainer Name and License No. P	inky's Environmental Sewer Service/	L1673
Maintenance Performed	Tank Measurement (must	be completed if tanks NOT pumped	i)
Tank(s) Pumped	Liquid Level of Tank i	n	
☐ Sludge and scum measured	Sludge Level in Tank i	n Scum Level in Tank in	
Do tanks need to be pumped?	Sludge + Scum / Liquid	d Level X 100	
\square Yes \square No (if no provide measurements)	= % Sludge & Scum	Tanks must be pumped if 25% or grea	ater
1. Access used to remove septage: Maintenan	ce Hole Other (enter authorization	code)	
2. Were all covers securely replaced? Yes	No		
3. Is there evidence of tank leakage from a septendence of damaged, cracked, or structural			or
Tank	Leaking Out Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐No ☐ Yes ☐No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?			
Tank #1 Sto gal Tank #2	gal Pretreatment tank	gal Pump Tank gal	
5. Other information: List any troubleshooting,	minor repairs conducted, tank sa	afety concerns, or other concerns.	
System to aid for ma	n he les		
		The state of the s	
6. Location of septage disposal:		0	