DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Mainten	ance 9-21-16 Reason	for Maintenance:	coutin) l	
Property Address: 11217 30th St N Property Owner's Name: Jeny Kressm					
Municipality:	ake Elno	State Zip Code 5	5042 GEO Coo	de/Property l.D. #: 47452gC	118
What w	as done to the system?	Tank Measur	ements (must be com	pleted if tanks NOT pumped)	STAY
	oed cum measured. d to be pumped? No (If no provide measuremen	Liquid Level of Tank _ Total (Sludge + Scum)	in. Sludge Le		in. - *
1. Access used to	remove septage: . Mainte	nance Hole Other (Go t	o #3 below)	 Tank must be pumped if this v is greater than 25%. 	ralue
2. If maintenance	hole was used, were all cover	s securely replaced?	s No please expla		
Explanation:	Tank is in-	flower gurde	is with	ock overit	
3. If owner refus them complet	es to allow a Subsurface Sev e and sign the following sta	vage Treatment System (S tement:	STS) to be pumped th	rough the maintenance hole, ha	ive
l,	(0	wner's name), refuse to allo	w the removal of solid	s and liquids through the mainten	ance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
6. How many ga	llons of septage were remov	ed?			
Tank #1 /50	Tank #2	Pretreatment Tank	Pretreatment Tank Pump Tank		
7. Other informa	ntion: List any troubleshooti	ng, minor repairs conducto	ed, tank safety conce	ns, or other concerns.	
8. Certification:	I hereby certify as a State of Mand made the observations, of				
Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 354 Afton, MN 55001					
Maintainer's Li	cense #: 1673 Mainta	iner's Phone #: 651-439-48	347		
Maintainer's Si	gnature //	Chips	Date: 🥎	-21-16	