833

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 9-7-16 Reason	for Maintenance:	orthe	C1946h4	013
Property Address: Syud 113th 5	Prope	rty Owner's Name: Tan	nmy Brune	tte
Municipality: Cottoge Grove	State Zip Code	35010 GEO Cod	e/Property I.D. #:	
What was done to the system?	Tank Mea	surements (must be com	pleted if tanks NOT pumpe	ed)
Tank(s) Pumped	Liquid Laural of Tax		in s	i.
Sludge and scum measured.	Liquid Level of Tan	k in. Sludge Le	vel in. Scum Level	in.
Do tanks need to be pumped?	Total (Sludge + Scu	m) / Liquid Leve	I = % Sludge & Scu	ım *
Yes No (If no provide measuremen	its)			
1. Access used to remove septage: Mainten			* Tank must be pumped if is greater than 25%.	this value
2. If maintenance hole was used, were all covers	s securely replaced?	res No please expla	in	
Explanation:				
3. If owner refuses to allow a Subsurface Sew them complete and sign the following stat	rage Treatment System ement:	(SSTS) to be pumped th	rough the maintenance ho	le, have
Ι,(ο	wner's name), refuse to	allow the removal of solids	and liquids through the ma	intenance
hole. I understand that removal of solids and	liquids through other a	ccess points is not conside	red maintenance.	
4. Is the tank designed as a leaky tank? example	: seepage pit, cesspool, di	ywell, leaching pit		
Tank#1 Yes No Verificatio Method	Used:		87 F	
Tank#2 Yes No Verificatio Method	l Used:			
5. Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound	eptic, holding, pretreat maintenance hole co	ment or pump tank belo	w the operating depth or e	vidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	Yes No		
6. How many gallons of septage were remove		[les [NO	Yes No	
	ear			
Tank #1 / SOO Tank #2	Pretreatment Ta	nk Pur	mp Tank	
7. Other information: List any troubleshootin				
Manhole is directly	under ref	coning wall. A	so access to a	vuer
8. Certification: I hereby certify as a State of M and made the observations, o	linnesota certified SSTS I	Maintainer that I personally	y conducted the work	
Maintainer's Name: PINKY'S SEWER SERVICE	Maintaine	r's Address: P.O. Box 354 A	Afton, MN 55001	
21 2	iner's Phone #: 651-439			
Maintainer's Signature	Clerm	Date: 9	7-16	