Pd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	rety to constitute a	valid maintenance	permit. This permi	t must be completed
prior to performing maintenance ac				
Date of Maintenance: //- みょり G Rea				
Property Address: 14975 Holms	toad AVR	Property Owner's	Name: <u>Geraid</u>	Miron
Municipality: Hugo ZIP: 5	Property Id	entification Numbe	r:	
Maintenance Permit No: 0916k5292			~	16
(ablication Represented	A Sinishe	kilire remotolosi a	e sem herselift anik	· Karromojeski
Tank(s) Pumped	Liquid Level of	Tank in	,	
☐ Sludge and scum measured	11			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage:	enance Hole 🗌 Other (enter authorization c	ode)	J
2. Were all covers securely replaced? 🖄 Yo	es 🗆 No			
Is there evidence of tank leakage from a evidence of damaged, cracked, or struct				rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes 🖾 No	☐ Yes ☐No	☐ Yes No	
Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☑ No	☐ Yes ♠No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons of septage were remove	ed?			
Tank #1 1500 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank				gal
. Other information: List any troubleshooting	ng, minor repairs cor	ducted, tank safet	y concerns, or othe	r concerns.