## 9-9

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance 9-23-16 Reason for Maintenance:			
Property Address: 8498 Stillwate	Prope	rty Owner's Name:	wid Herder
Municipality: Lake Elmo	State Zip Code	55048 GEO CO	de/Property I.D. #: 018829 4995
What was done to the system?	Tank Mea	surements (must be con	npleted if tanks NOT pumped)
Tank(s) Pumped			
Sludge and scum measured.	Liquid Level of Tan	k in. Sludge L	evel in. Scum Level in.
Do tanks need to be pumped?	Total (Sludge + Scu	\	*
Yes No (If no provide measurement	rotal (sludge + scc	ım) / Liquid Lev	el = % Sludge & Scum
1. Access used to remove septage: Mainten			<ul> <li>Tank must be pumped if this value is greater than 25%.</li> </ul>
2. If maintenance hole was used, were all covers	securely replaced?	Yes No please explo	ain
Explanation: System for of	al for may	choice	
3. If owner refuses to allow a Subsurface Sewa them complete and sign the following state	age Treatment System	(SSTS) to be pumped the	nrough the maintenance hole, have
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 Ves No Verificatio Method Used:			
Tank#2 Yes No Verificatio Method Used:			
5. Is there evidence of tank leakage from a seg damaged, cracked, or structurally unsound	otic, holding, pretreat maintenance hole cov	ment or pump tank belovers?	ow the operating depth or evidence of
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	☐ Yes ☐ No	T Yes T No	☐ Yes ☐ No
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No
6. How many gallons of septage were removed		_ res _ res	L les L No
Tank #1 CO Tank #2 GOV Pretreatment Tank Pump Tank			
7. Other information: List any troubleshooting	g, minor repairs condu	cted, tank safety conce	rns, or other concerns.
8. Certification: I hereby certify as a State of Min and made the observations, or	directly supervised oth	ers in the performance of	this job.
Maintainer's Name: PINKY'S SEWER SERVICE	Maintaine	r's Address: P.O. Box 354	Arton, MN 55001
Maintainer's License #: 1673 Maintain	er's Phone #: 651-439	-4847	
Maintainer's Signature	fl Clin	Date: 9	-23-16