PM



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must b	pe completed in its entirety	to constitute a v	alid maintenance p	ermit. This permit	must be completed
prior to perf	orming maintenance activi	ties and remain o	n-site for the durat	ion of the maintena	ance activity.
Date of Maintenance	: 11-10-16 Reason	n for Maintenance:	Rayslar		
	130 182 nd St W			ame: Toda &	Pohnen
Municipality:	+ (ake ZIP: 55	Property Ide	entification Number		
	No: 1548465280				<b>V</b>
Akintei	ana Performed - Table		girana i Innstru	sangers III ans	Nexe origin - B
Tank(s) Pumped Liquid Level of Tank in					
☐ Sludge and scum measured Sludge Level in Tank in Scum Level in Tank					
Do tanks need to be pumped?   Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	um Tar	nks must be pumped	if 25% or greater
1. Access used to re	move septage: Maintena	nce Hole 🗌 Other (	enter authorization co	de)	<i>,</i>
2. Were all covers so	ecurely replaced? Yes	□No			•
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes ☒No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes ☐No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1750 gal Tank #2 1300 gal Pretreatment tank gal Pump Tank				Pump Tank	gal gal
. Other information	: List any troubleshooting,	minor repairs cor	nducted, tank safet	y concerns, or othe	r concerns.
. Location of septage	e disposal: Metro				