Pd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

	This section must be completed in its entire	ety to constitute a	valid maintenance	permit. This perm	it must be completed		
	prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
	Date of Maintenance: 8-22-19 Reason for Maintenance: Regular maintenance						
	Property Address: 17077 Quail	Aue N	Property Owner's	Name: Oj.	Plenhart		
	Municipality: Still water ZIP: 5	5087 Property Id	dentification Numb	er:			
	Maintenance Permit No: <u>68219 k 4031</u>	Maintainer Name	and License No.	SSI-#2	10		
TO SECURE	Maintenance Performed	Tank Me	asurement (must l	oe completed if tank	s NOT pumped)		
N	Tank(s) Pumped	Liquid Level of	Tank i	n			
[Sludge and scum measured	Sludge Level ir	Tank ir	Scum Level in Tan	k in		
	Do tanks need to be pumped?	Sludge + Scum	/ Liquid	Level X 10	0		
L	☐ Yes ☐ No (if no provide measurement			anks must be pumped			
1	. Access used to remove septage: Mainter	nance Hole 🗌 Other	(enter authorization	code)	<i>'</i>		
	. Were all covers securely replaced? X Yes						
3	. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	eptic, holding, pret Irally unsound mai	reatment or pump ntenance hole cov	tank below the ope ers?	erating depth or		
	Tank	Leaking Out	Leaking In	Cover Damage			
	Septic/Holding Tank #1	☐ Yes X No	☐ Yes 风No	☐ Yes 🕅 No			
	Septic/Holding Tank #2	☐ Yes XINo	☐ Yes ☐No	☐ Yes XNo			
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
4.	How many gallons of septage were removed	! ?		de la companya de la			
	Tank #1 100 gal Tank #2 1000	gal Pretreatment	tank ga	al Pump Tank	gal		
5.	Other information: List any troubleshooting						
					▼		
6.	Location of septage disposal:						



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

		COLOR DATE OF THE STREET		NAME OF TAXABLE PARTY.	
This section must	be completed in its entirety	to constitute a	valid maintenance p	ermit. This permit	must be complet
<u>prior</u> to per	forming maintenance activi	ties and remain	on-site for the durat	ion of the mainten	ance activity.
Date of Maintenanc		for Maintenance	: Maintenena	ce Due	P
Property Address:	13500 2054 54	N Scandi	Property Owner's N	ame: Nick	Vannelli
Municipality:	Condia zip: 55	073 Property Id	lentification Number:		
I	No: 03692 r4030			2	V
Mainter	ance Performed	Tank Me	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in	·	
☐ Sludge and scum	measured	Sludge Level in	Tank in	Scum Level in Tank	in
Do tanks need to	be pumped?		/ Liquid Le		
☐ Yes ☐ No (i	f no provide measurements)	11	cum Tan		
1. Access used to re	move septage: Maintenan	ce Hole Other	enter authorization cod	de)	J
2. Were all covers se	ecurely replaced? 🛛 Yes 🛭	□No			
Is there evidence evidence of dam	of tank leakage from a sept aged, cracked, or structura	tic, holding, pret Ily unsound mair	reatment or pump to tenance hole covers	ank below the oper s?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons	of septage were removed?	u .			
Tank #1	of septage were removed?	gal Pretreatment	tank gal	Pump Tank	gal
	List any troubleshooting, n	ninor repairs con			
Location of septage	disposal:				
·	uisposat.				





14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must be	completed in its entirety	the constitute of				
nins section must be	completed in its entirety	to constitute a	valid maintenance p	permit. This permit	must be comple	
	prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance:	8-19-16 Reason	for Maintenance	: Pim,			
Property Address:	870 202nd	Stroot	Property Owner's N	lame: John Co	addy	
Municipality:	zip:555	SProperty Id	lentification Number	•		
Maintenance Permit N	10: <u>f640963278</u>				D	
Maintena	nce Performed	Tank Me	surement (must be	completed if tanks i	(OT pumped)	
Tank(s) Pumped		Liquid Level of	Tank in			
Sludge and scum m	easured	Sludge Level ir	Tank in	Scum Level in Tank_	in	
Do tanks need to b	nks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if r	no provide measurements)	11		ks must be pumped if	25% or greater	
1. Access used to rem	ove septage: Maintenar	ce Hole Dther	enter authorization co	de) Prop Pipe	J	
	urely replaced? Yes			, , , ,	1	
 Is there evidence of damage 	f tank leakage from a sept ged, cracked, or structura	tic, holding, pret Ily unsound mair	reatment or pump to tenance hole cover	ank below the opera s?	ting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
9	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
ı	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
·	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of	septage were removed?					
Tank #1 (4(1)	gal Tank #2	gal Pretreatment	tankgal	Pump Tank	gal	
5. Other information: L	ist any troubleshooting, r					
				-		





14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must I	be completed in its entiret	v to constitute a	valid maintenance	permit This permi	t must be sempleted
prior to per	forming maintenance activ	ities and remain	on-site for the dur	ation of the mainter	t must be completed
Date of Maintenance	e: 8-19-16 Reason	n for Maintenance	: P. M		
Property Address: 1	4084 saucela	the trail	Property Owner's	Name: Chas + tra	cy minisor
Municipality:	haate ZIP:	Property Id	dentification Numbe	er:	
Maintenance Permit	No: 40849 x 3277	Maintainer Name	and License No.	SSI - #2	16
Mainten	ance Performed	Tank Me	asurement (must b	e completed if tank	s NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in		
☐ Sludge and scum	measured	Sludge Level in	Tankin	Scum Level in Tank	(in
Do tanks need to	be pumped?			Level X 10	
☐ Yes ☐ No (if	no provide measurements)	11		anks must be pumped	2 22
	move septage: Maintenal		(enter authorization c	ode)	,
3. Is there evidence	of tank leakage from a sep aged, cracked, or structura	tic, holding, pret	reatment or pump	tank below the ope	rating depth or
		any ansound man			
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ĦÑo	☐ Yes ♥No	
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ❤️No	☐ Yes ❷No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 (())			tankga		gal
5. Other information: IN Halled 1	List any troubleshooting, 1344 TNS pectucn	minor repairs cor		y concerns, or othe	r concerns.
5. Location of septage	disposal:				



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must	be completed in its entiret	y to constitute a	valid maintenance	permit This permi	t must be complet
prior to per	forming maintenance activ	ities and remain	on-site for the dura	tion of the mainter	ance activity
,					
Property Address: _/	e: 17Acz 16 Reason	250 °	Property Owner's N	Name: Town E	der
Municipality: /4 0 n	ZIP: 550	38 Property Id	entification Number	•	
Maintenance Permit	No: 17/881/4029	Maintainer Name	and License No.	3SI - #2	16
Mainten	ance Performed	Tank Me	isurement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in	·	
☐ Sludge and scum	measured	Sludge Level ir	Tank in	Scum Level in Tank	in
Do tanks need to	be pumped?	Sludge + Scum	/ Liquid L	evel X 100	0
☐ Yes ☐ No (ii	no provide measurements)	= % Sludge & So	cum Tar	nks must be pumped	if 25% or greater
2. Were all covers se3. Is there evidence	move septage: Maintenal ecurely replaced? Yes of tank leakage from a sep aged, cracked, or structura	□ No tic, holding, pret	reatment or pump (tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ♥No	☐ Yes ☐ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	80			
		gal Pretreatment	tank gal	Pump Tank	gal
Tank #1 /520	of septage were removed? _ gal Tank #2 List any troubleshooting,				

Pd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section mus	t be completed in its entire	ety to constitute a	valid maintenance	nermit This permit	must be comple
prior to pe	erforming maintenance act	ivities and remain	on-site for the du	ration of the maintena	nnost be comple
	rce: 1944 / Reas				
Property Address:	23920 July Ave 1	V	Property Owner's	s Name: King LC lind	2.)=(====
Municipality: Sa.		Property I			y Johnson
Maintenance Perm	it No: <u>X2721e 327</u>				<i>Φ</i>
Mainte	Phance Performed	Tank Me	asurement (must l	oe completed if tanks	NOT pumped)
Tank(s) Pumpe	d	Liquid Level o	Tanki	n	es Uni
☐ Sludge and scur	n measured	Sludge Level in	Tank i	Scum Level in Tank_	in
Do tanks need	*	Sludge + Scum	/ Liquid	Level X 100	
☐ Yes ☐ No	(if no provide measurement			anks must be pumped i	f 25% or greater
	remove septage: Mainter		(enter authorization	code)	<i>,</i>
2. Were all covers	securely replaced? Yes	□ No			
3. Is there evidenc evidence of dar	e of tank leakage from a se maged, cracked, or structu	eptic, holding, pret rally unsound mai	reatment or pump ntenance hole cov	tank below the opera ers?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes ☐No	☐ Yes ☒No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☒No	☐ Yes ☑No	☐ Yes ☒No	
. How many gallons	of septage were removed	?			
Tank #1 /109	gal Tank #2	gal Pretreatment	tank ga	al Pump Tank \$26	gal
Other information	: List any troubleshooting	, minor repairs cor	ducted, tank safe	ty concerns, or other of	concerns.
Name of the last o					
Location of septage	e disposal:				

80



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must be	completed in its entiret	y to constitute a v	alid maintenance ¡	permit. This permit	must be complete
<u>prior</u> to perfo	rming maintenance activ	ities and remain o	n-site for the dura	tion of the mainten	ance activity.
Date of Maintenance:	8-16-16 Reaso	n for Maintenance:	Marntenano	e Pumping	:4
	921 Quint Ave			(/	Swim
Municipality: 📉 🛭	zip: 530	97 Property Ide	entification Number	r:	
	10:17153 2321				V
Maintena	nce Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in		
☐ Sludge and scum r	neasured	Sludge Level in	Tank in	Scum Level in Tank	in
Do tanks need to	be pumped?	Sludge + Scum	/ Liquid	Level X 100)
☐ Yes ☐ No (if	no provide measurements) = % Sludge & Sc	um Ta	nks must be pumped	if 25% or greater
1. Access used to rer	nove septage: Mainten	ance Hole 🗌 Other (enter authorization c	ode)	J
2. Were all covers se	curely replaced? 🛭 Yes	□ No			4
	of tank leakage from a se aged, cracked, or structu				rating depth or
SA.	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒ No	☐ Yes 🛭 No	☐ Yes 🎖 No	
	Septic/Holding Tank #2	☐ Yes 🎖 No	☐ Yes ☑ No	☐ Yes ☑ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	1?			
Tank #1 /600	gal Tank #2 911	gal Pretreatment	tank ga	al Pump Tank	gal
5. Other information:	List any troubleshooting	, minor repairs cor	nducted, tank safe	ty concerns, or other	er concerns.
6. Location of septage	disposal: Metro Lw	R			

Pd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must be	completed in its entiret	y to constitute a v	alid maintenance p	ermit. This permit	must be complete
<u>prior</u> to perfo	rming maintenance activ	ities and remain o	n-site for the durat	ion of the mainten	ance activity.
Date of Maintenance:	8-16-14 Reason	n for Maintenance:			
Property Address:	3128 170th 57		Property Owner's N	lame: Lo:5 4	Elsenpeter
Municipality:	ZIP: 55	047 Property Ide	entification Number	:	
Maintenance Permit N	10t06043272			1	V
Maintena	nce Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in		
☐ Sludge and scum n	neasured	Sludge Level in	Tank in	Scum Level in Tank	(in
Do tanks need to	be pumped?	Sludge + Scum _	/ Liquid L	.evel X 10	0
☐ Yes ☐ No (if	no provide measurements) = % Sludge & Sc	um Tai	nks must be pumped	l if 25% or greater
	nove septage Aaintena curely replaced?		enter authorization co	ode)	
	of tank leakage from a se aged, cracked, or structu				erating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	•
	Septic/Holding Tank #1	☐ Yes 🖺 No	☐ Yes 🎖 No	☐ Yes ¶No	
	Septic/Holding Tank #2	☐ Yes 🗷 No	☐ Yes ₹No	☐ Yes ► No	
	Pretreatment Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	l?			
Tank #1 /000	gal Tank #2 1000	gal Pretreatment	tankga	l Pump Tank	gal
	List any troubleshooting				er concerns.
4 Logation of sortes	dienosale	2			
Location of septage	uisposat:				





14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

	e completed in its entirety				
<u>prior</u> to perfo	rming maintenance activi	ties and remain o	n-site for the duration	on of the maintena	nce activity.
Date of Maintenance:	8-15-16 Reason	for Maintenance:	P.M.		· · · · · · · · · · · · · · · · · · ·
Property Address:	1711 215th St	- North	Property Owner's Na	me: Duct & L	Ayton cohoe
Municipality:	John ZIP:	Property Ide	entification Number:		
Maintenance Permit N	40: N6562-0327	Maintainer Name a	nd License No. OS	ST - #211	V
Maintena	nce Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in		
☐ Sludge and scum n	neasured	Sludge Level in	Tank in	Scum Level in Tank	in
Do tanks need to		Sludge + Scum	/ Liquid Le	vel X 100	
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	um Tank	ks must be pumped	if 25% or greater
	nove septage:		enter authorization cod	le) pumped thru	6"p.p2
	of tank leakage from a sep aged, cracked, or structur				ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed:	,			
Tank #1 1120	gal Tank #2	gal Pretreatment	tankgal	Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs cor	nducted, tank safety	concerns, or othe	r concerns.
			8		
6. Location of septage	disposal:				



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must be completed in its entirety t	to constitute a v	alid maintenance p	ermit. This permi	t must be complete
prior to performing maintenance activities	es and remain o	n-site for the durat	ion of the mainten	ance activity.
Date of Maintenance: 8-15-10 Reason f	for Maintenance:	Pm.		
Property Address: 21970 mponing	trail north	Property Owner's N	lame Lewis & R	ita Berge
Municipality: Scandia ZIP:	Property Id	entification Number	:	9
Maintenance Permit No: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	aintainer Name a	and License No.	SSI - #2	16
Maintenance Performed	Tank Mea	surement (must be	completed if tank	s NOT pumped)
Tank(s) Pumped	Liquid Level of	Tank in		
Sludge and scum measured	Sludge Level in	Tank in	Scum Level in Tanl	k in
Do tanks need to be pumped?	Sludge + Scum	/ Liquid L	evel X 10	0
☐ Yes ☐ No (if no provide measurements)	= % Sludge & So	um Tar	nks must be pumped	d if 25% or greater
1. Access used to remove septage: Maintenance	e Hole 🗌 Other (enter authorization co	ode)	y
2. Were all covers securely replaced? es	No			(
3. Is there evidence of tank leakage from a septi evidence of damaged, cracked, or structural				erating depth or
Tank	Leaking Out	Leaking In	Cover Damage	•
Septic/Holding Tank #1	☐ Yes KNo	☐ Yes 🗹 No	☐ Yes ☐ No	•
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?	ė			
Tank #1 (640) gal Tank #2 g	al Pretreatmen	tank ga	l Pump Tank	gal
5. Other information: List any troubleshooting, m	ninor repairs co	nducted, tank safet	y concerns, or other	er concerns.
6. Location of septage disposal:				



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must b	e completed in its entirety	to constitute a v	alid maintenance	permit. This permi	t must be complet
prior to perfo	orming maintenance activit	ies and remain o	n-site for the dura	tion of the mainten	ance activity.
Date of Maintenance	59-14 Reason	for Maintenance:	Dw.		
Property Address:	2375 upper Healf	er pue sul	Property Owner's I	Name: Aurie	Car(SUN)
Municipality:	zip: 550	758 Property Ide	entification Numbe	r:	
Maintenance Permit I	40:dle09503265A	— Naintainer Name a	nd License No.	SSI - #2	16
Maintena	ance Performed	Tank Mea	surement (must be	e completed if tank	s NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in		
☐ Sludge and scum i	measured	Sludge Level in	Tank in	Scum Level in Tank	c in
Do tanks need to	be pumped?	Sludge + Scum	/ Liquid	Level X 10	0
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	um Ta	nks must be pumped	f if 25% or greater
1. Access used to rea	move septage: Maintenar	nce Hole \square Other (enter authorization c	ode)	<i>,</i>
2. Were all covers se	curely replaced? Yes	□ No			,
	of tank leakage from a septaged, cracked, or structura				erating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 収ේ	☐ Yes \\	☐ Yes 🗖 Yeo	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ Yo	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	*			
Tank #1 1500	gal Tank #2 WW	gal Pretreatment	tankg	al Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs cor	nducted, tank safe	ty concerns, or oth	er concerns.
6 Location of sentage	disposal:				



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must be	e completed in its entirety	to constitute a	alid maintenance ¡	permit. This permit	must be complete
<u>prior</u> to perfo	orming maintenance activit	ies and remain o	on-site for the dura	tion of the mainten	ance activity.
Date of Maintenance:	Col-llo Reason	for Maintenance	P.M.		
Property Address:	1694 McDonard 5	or place	Property Owner's I	Name: Steve or	gren
Municipality:	ZIP:	Property Id	entification Number	r:	
	No: 18944x 1337 N			And the second s	lle
Maintena	ince Performed	Tank Mea	asurement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of	Tank in		
\square Sludge and scum r	neasured	Sludge Level in	Tank in	Scum Level in Tank	in
Do tanks need to	be pumped?	Sludge + Scum	/ Liquid I	_evel X 100)
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & So	cum Ta	nks must be pumped	if 25% or greater
2. Were all covers se 3. Is there evidence	nove septage: Maintenanceurely replaced? Yes of tank leakage from a septaged, cracked, or structural	☐ No ic, holding, pret	reatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes ♀No	☐ Yes ☐	
	Septic/Holding Tank #2	☐ Yes ♀No	☐ Yes ₩No	☐ Yes ৺No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ♀No	☐ Yes ☒No	
4. How many gallons	of septage were removed?				
Tank #1 (1)20	gal Tank #2 1000 g	gal Pretreatmen	t tank ga	l Pump Tank	gal
	List any troubleshooting, r				





14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

This section must be	e completed in its entirety	y to constitute a v	alid maintenance	permit. This permit	must be completed		
<u>prior</u> to perfo	rming maintenance activi	ities and remain o	n-site for the dur	ation of the mainten	ance activity.		
	8-4-16 Reason						
Property Address: 2	001 230th ST		Property Owner's	Name: Richard	1 Ahlstrom		
Municipality:	est Lahe ZIP: 550	Property Ide	entification Numbe	er:			
	Ho: j2223K324);		2	V		
Maintena	nce Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)		
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to	be pumped?	Sludge + Scum .	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to ren	nove septage: Maintena	ince Hole \square Other (enter authorization	code) though pin	u very deep		
2. Were all covers se	curely replaced? Yes	□ No					
	of tank leakage from a sep aged, cracked, or structur				rating depth or		
	Tank	Leaking Out	Leaking In	Cover Damage			
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
4. How many gallons	of septage were removed	?					
Tank #1 1240 gal Tank #2 g		gal Pretreatment tank gal		gal Pump Tank	gal		
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.		
6. Location of septage	disposal:						



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Pd

This section must be completed in its entire	ety to constitute a v	alid maintenance	permit. This permit	must be complete		
<u>prior</u> to performing maintenance act	ivities and remain o	n-site for the dura	tion of the maintena	nce activity.		
Date of Maintenance: 8-1-16 Rea	son for Maintenance:	P.M.				
Property Address: 23545 Jense		1	Name: Lisa + Bill	y Toe franch		
Municipality: ZIP:			100 market 200 m - 100			
Maintenance Permit No: <u>e 3468h 325</u>				<u> </u>		
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank in				
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measuremen	ts) = % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Access used to remove septage: Mainte Were all covers securely replaced? Ye 		enter authorization o	ode)	,		
Is there evidence of tank leakage from a sevidence of damaged, cracked, or struct				ating depth or		
Tank	Leaking Out	Leaking In	Cover Damage			
Septic/Holding Tank #1	☐ Yes 🗘 No	☐ Yes 🖾 No	☐ Yes XXNo			
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
4. How many gallons of septage were remove	ed?					
Tank #1 200 gal Tank #2	gal Pretreatment	t tankg	al Pump Tank	gal		
5. Other information: List any troubleshooting				r concerns.		
		9				
5. Location of septage disposal:						