

6.

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its ent	tirety to constitute	valid maintenance	e permit. This per	nit must be complete
<u>prior</u> to performing maintenance a	ctivities and remain	on-site for the du	ration of the mainte	enance activity.
Date of Maintenance: 1-29-16 Re				•
Property Address: 9685 Starbi	idge Trl	Property Owner's	Name: Dorrell	Roberts
Municipality: Styluster ZIP:	SOSZ Property	dentification Numb	er:	
Maintenance Permit No: V 6985w52				
Authretaliges perintifiers, it	A A A A A A A A A A A A A A A A A A A	रके भाग को है जिल्हा	e den idaz iri sin	es rest single like
Tank(s) Pumped	Liquid Level o	f Tank ir	1	
\square Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurement			anks must be pumpe	
. Access used to remove septage: Amaint . Were all covers securely replaced? Ye . Is there evidence of tank leakage from a evidence of damaged, cracked, or struct	es □No septic, holding, pref	reatment or pump	tank below the on	erating depth or
Tank	Leaking Out	Leaking In	Cover Damage	-
Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes ⊠No	☐ Yes ☑No	-
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
How many gallons of septage were remove	ed?			
Tank #1 // gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	gal
Other information: List any troubleshootin				er concerns.
Location of septage disposal:				