Pd



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	be completed in its entirety	to constitute a	valid maintenance	permit. This perm	it must be completed
prior to per	forming maintenance activity	ties and remain	on-site for the dur	ation of the mainter	nance activity.
Date of Maintenance	e: 11-29-16 Reason	for Maintenance	: Pimi		
Property Address: 1422 230th St Property Owner's Name: T. m Much					
Municipality:	ZIP:	Property I	dentification Numbe	er:	
Maintenance Permit	No:3747035 Z 9.5 M	Maintainer Name	and License No.	SSI - #2	10
1 Aunte	eiste Reproduced	图:36 76	ស់វាលាស់ព្រះពេស។	eveniuete in confe	e filescoping all
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	be pumped?	Sludge + Scum / Liquid Level X 100			
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or great					if 25% or greater
2. Were all covers so 3. Is there evidence	ecurely replaced? Aaintenan of tank leakage from a sept aged, cracked, or structural	No ic, holding, pre	reatment or pump	tank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons	of septage were removed?	ž			
Tank #1 500	gal Tank #2 500 g	al Pretreatment	tank 700 ga	l Pump Tank	gal
Other information:	List any troubleshooting, m	inor repairs cor	nducted, tank safet	y concerns, or othe	r concerns.
Location of centage	disposal:				