

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 6-24-16 Reason for Maintenance: Rowline - Vental					
Property Address: 16460 upper 22nd 5+ 5 Property Owner's Name: Sam Aco					
Municipality: Landen ZIP: 58243 Property Identification Number:					
Maintenance Permit No: 2345400898 Maintainer Name and License No. SMIMER 1981					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? ✓ Yes ☐ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
3	Tank	Leaking Out	Leaking In	Cover Damage	
,	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes ☑No	☐ Yes ᡬNo	
	Septic/Holding Tank #2	☐ Yes ⊠No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
	_ gal Tank #2		tankga		gal gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					