

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730



Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
prior to perform	ming maintenance activiti	es and remain on-	site for the duration	on of the maintenar	nce activity.
Date of Maintenance: _	5/27-16 Reason 1	for Maintenance: _	Routine	-	
Property Address:	1331 300 St	P	roperty Owner's Na	me: Kerry 1	lonsrud
Municipality: SV	SaulforkZIP: 550,	7 \ Property Ider	tification Number:	,	
	Tagnal			chlomka ser	1 7909
Maintenance Permit No	0: <u>4005516903</u> M	amtamer Name an	d License No.	MOTTAL SA	V 2181
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
	nove septage: Maintenar		nter authorization co	de)	
2. Were all covers securely replaced? ✓ Yes □ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒ No	☐ Yes ☒ No	☐ Yes ☒No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 (760 gal Tank #2		gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
A HARMAN STREET, STREE	***				
					-