DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

| Date of Maintena | ince 10-24-16 Reason | for Maintenance: 3 | Year | | | |
|--|---|-----------------------------------|---|-------------------------------|----------|--|
| Property Address | 19860 Man | ning TRL proper | ty Owner's Name: | ancy Anton | son | |
| Municipality: | | State ///Zjo Code | 5302 SGEO Cod | e/Property I.D. #: | | |
| What wa | as done to the system? | Tank Meas | Tank Measurements (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? | | Liquid Level of Tank | | | in. — | |
| Ses 🗆 | No (If no provide measuremer | nts) | | | | |
| 1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%. | | | | | | |
| 2. If maintenance | hole was used, were all cover | s securely replaced? | Yes No please expla | in | | |
| Explanation: | | • | · | | | |
| | es to allow a Subsurface Sev e and sign the following stat | | (SSTS) to be pumped th | rough the maintenance hole, | have | |
| l, | (0 | wner's name), refuse to a | illow the removal of solids | and liquids through the maint | enance | |
| hole. I underst | and that removal of solids and | l liquids through other a | ccess points is not conside | red maintenance. | | |
| 4. Is the tank desi | gned as a leaky tank? <i>example</i> | : șeepage pit, cesspool, dr | ywell, leaching pit | | | |
| Tank#1 🗌 Ye | s (Verificatio Method | d Used: | ¥ | | | |
| Tank#2—— Ye | s No Verificatio Method | T Used: | | | | |
| 5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | • | |
| , | Septic/Holding Tank #1 | Yes No | Yes No | Yes No | | |
| ` | Septic/Holding Tank #2 | Yes No | Yes No | Yes No | | |
| .• | Pretreatment Tank | Yes N | ☐ Yes ☐ Nø | Yet No | | |
| | Pump Tank | ☐Yes ☐No | Yes No | ☐ Yes ☐ No | | |
| 6. How many gal | llons of septage were remov | red? | | | | |
| Tank #1 500 | Tank #2 | Pretreatment la | nk Pui | mp Tank | - | |
| 7. Other informa | ation: List any troubleshooti | ng, minor repairs condi RG FFI | ucted, tank safety concer | rns, or other concerns. | | |
| 8. Certification: | Thereby certify as a State of N | Ainnesota certified SSTS | Maintainer that I personal | v conducted the work | | |
| | and made the observations, | or directly supervised oth | ners in the performance of | this job. | | |
| Maintainer's Na | ame: Hassle Free Septic | Maintaine | er's Address: P.O. Box 702 | North Branch, MN 55056 | | |
| Maintainer's Li | cense #: L3287 Mainta | niner's Phone #: 763-223 | 2-4397 | - 2// 1/ | | |
| Maintainer's Signature M2 Date: 10-24-16 | | | | | | |