DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 1-8-16 Reason for N	Maintenance: 3	verr		
Property Address: 14150 Sand.	a TRL Property	Owner's Name:	et Jorgenso	<u>^</u>
Municipality: St	ate MZip Code	55073 GEO Code	e/Property I.D. #:	
What was done to the system?	Tank Measu	rements (must be com	pleted if tanks NOT pumped)	
Sludge and scum measured.	Liquid Level of Tank in. Sludge Level in. Scum Level in.			
Do tanks need to be pumped? Yes No (if no provide measurements)	Total (Sludge + Scum)/ Liquid Leve		
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%.				
2. If maintenance hole was used, were all covers se	curely replaced? 📈	(es 🔲 No please explai	-	
Explanation:				
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:				
I, (owne	er's name), refuse to all	ow the removal of solids	and liquids through the mainte	nance
hole. I understand that removal of solids and liqu	uids through other acc	ess points is not conside	red maintenance.	
4. Is the tank designed as a leaky tank? example: see	epage pit, cesspool, dryv	vell, leaching pit	* 4	
Tank#1 ☐ Yes ☑ No Verificatio Method Us	ed:			
Tank#2 Yes No Verificatio Method Us	ed:	,	·	
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
Tank	Leaking Out	Leaking In	Cover Damage	•
Septic/Holding Tank #1	Yes No	Yes No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were removed?	?			
Tank #1 /500 Tank #2	Pretreatment (an	Pui	mp Tank / oco	
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				
8. Certification: I hereby certify as a State of Minr and made the observations, or d	irectly supervised othe	rs in the performance of	this job.	
Maintainer's Name: Hassle Free Septic Maintainer's Address: P.O. Box 702 North Branch, MN 55056				
Maintainer's License #: L3287 Maintaine	r's Phone #: 763-222-	<u> </u>	10-11	
Maintainer's Signature 2022 h		Date: //	1-8-16	