DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

| | 11 17 1/ 5 | SSTS MAINTEN | ANCE REPORT | • |
|-------------------|---|---------------------------|----------------------------|--|
| Date of Maintena | ance // -/ /O _{Reasor} | n for Maintenance: | Veal | |
| Property Address | : 19039 Lak | Spar Ave Prope | rty Owner's Name: | mon Bruce |
| Municipality: | | State Mr. Zip Code | GEO Co | ode/Property I.D. #: |
| What w | as done to the system? | Tank Mea | surements (must be co | mpleted if tanks NOT pumped) |
| Tank(s) Pump | ped . | Liquid Level of Tan | k in. Sludge I | Level in. Scum Level in. |
| | cum measured. | Liquid Level of Tan | in. Sludge | Perel Scall Ferel |
| Yes | d to be pumbed? No (If no provide measureme | ents) Total (Sludge + Scu | ım) Liquid Lev | = % Sludge & Scum |
| 1. Access used to | remove septage: Mainte | enance Hole | Go to #3 below) | * Tank must be pumped if this value is greater than 25%. |
| 2. If maintenance | hole was used, were all cove | rs securely replaced? | es ∏No please expl | |
| Explanation: | | | | |
| 3. If owner refus | es to allow a Subsurface Se e and sign the following sta | | n (SSTS) to be pumped t | through the maintenance hole, have |
| t, | | owner's name) refuse to | allow the removal of soli | ds and liquids through the maintenance |
| hole. I underst | and that removal of solids an | | | |
| | gned as a leaky tank? exampi | _ | • | |
| Tank#1 ☐ Ye | s No Verificatio Metho | hd Used: | • | |
| | | | | |
| Tank#2 Te | s No Verificatio Metho | od Used: | | |
| | nce of tank leakage from a s ked, or structurally unsour | | | low the operating depth or evidence o |
| , | Tank | Leaking Out | Leaking In | Cover Damage |
| | Septic/Holding Tank #1 | ☐ Yes No | Yes 🖪 No | Yes No |
| | Septic/Holding Tank #2 | ☐ Yes ⑤No | Yes No | Yes No |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | Yes No |
| | Pump Tank | ☐ Yes 🖃 No | ☐ Yes No | Yes No |
| 6. How many gai | lons of septage were remo | ved? | • | |
| Tank #1 /000 | () Tank #2 /000 | Pretreatment Ta | nk P | ump Tank 1000 |
| 7. Other informa | tion: List any troubleshoot | ing, minor repairs cond | ucted, tank safety conc | erns, or other concerns. |
| 8. Certification: | I hereby certify as a State of and made the observations, | or directly supervised ot | ners in the performance o | of this job. |
| Maintainer's Na | ame: Hassle Free Septic | Maintaine | er's Address: P.O. Box 702 | 2 North Branch, MN 55056 |
| Maintainer's Li | cense #: L3287 Maint | ainer's Phone #: 763-22 | | , |
| Maintainer's Si | gnature n 2 | | Date: | 1-17-16 |