

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance p	ermit. This permit n	nust be completed
prior to perform	ming maintenance activiti	es and remain on	site for the dura	tion of the maintenar	nce activity.
Date of Maintenance: _	7 - 1 - 16 Reason t	for Maintenance: _	Rowthe		
Property Address:	85 Sagth St	F	roperty Owner's N	Name: Johne &	Specch
Municipality: 5 ?	P ZIP:5507	Property Idea	ntification Number	:	
Maintenance Permit No	:1417154091Z M	aintainer Name ar	nd License No	Schlomka Sc	N 2989
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
⊠ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? Yes [of tank leakage from a sep ged, cracked, or structura	tic, holding, pretr	eatment or pump tenance hole cov	o tank below the oper ers?	rating depth or
,	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	□ Yes 🛛 No	☐ Yes ☒ No	□ Yes 🏿 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🗖 No	☐ Yes ☑ No	☐ Yes 🕅 No	
4. How many gallons	of septage were removed	?			
Tank #1 \SO gal Tank #2		gal Pretreatmen	t tank	gal Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs co	nducted, tank saf	ety concerns, or other	er concerns.