DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 120-16 Reason for	Maintenance:	Neco	<i>人</i> ,大	
Property Address: 9330 - 239 //	S+ Propert		Diane Bowersox	_
Municipality:	State M Zip Code	55025 GEO	Code/Property I.D. #:	
What was done to the system?	Tank Meası	irements (must be	completed if tanks NOT pumped)	
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped?	Liquid Level of Tank Total (Sludge + Scun		ge Level in. Scum Level in Level = % Sludge & Scum	*
Yes No (If no provide measurements)			* Tank must be pumped if this valu	
1. Access used to remove septage: Maintena			is greater than 25%.	
2. If maintenance hole was used, were all covers s	ecurely replaced? 🔀 ្	res No please e	xplain	
Explanation:	,			_
3. If owner refuses to allow a Subsurface Sewage them complete and sign the following statem		SSTS) to be pumpe	ed through the maintenance hole, have	
I, (owr	ner's name), refuse to all	ow the removal of s	solids and liquids through the maintenance	:e
hole. I understand that removal of solids and lid			·	
4. Is the tank designed as a leaky tank? <i>example: se</i>	epage pit, cesspool, dry	well, leaching pit		
Tank#1 Yes No Verificatio Method U	sed:			
Tank#2 Yes No Verificatio Method U	sed:	i ne per de station (notation of the state o	W-1 West-Indian	
5. Is there evidence of tank leakage from a sept damaged, cracked, or structurally unsound n			below the operating depth or evidence	of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes No	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
6. How many gallons of septage were removed	?			
Tank #1 /500 Tank #2	Pretreatment Tanl	(Pump Tank	
7. Other information: List any troubleshooting	minor repairs conduct	eted, tank safety co	ncerns, or other concerns.	
8. Certification: Thereby certify as a State of Min and made the observations, or o	nesota certified SSTS M	aintainer that I pers	onally conducted the work ce of this job.	_
Maintainer's Name: Hassle Free Septic		•	702 North Branch, MN 55056	
Maintainer's License #: L3287 Maintaine	er's Phone #: 763-222-		a 2. //	
Maintainer's Signature	i garta esta antica de la calenta de la cale	Date:	9-26-16	