DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintena	nce 9-21-16 Reason for	Maintenance: 3	rear		
Property Address:	7634 - 13714	Proper	ty Owner's Name:	ich Rivarc	4
Municipality: State // Zip Code ESD // Zip Code/Property I.D. #:					
What wa	s done to the system?	Tank Meas	urements (must be con	npleted if tanks NOT pumpe	d)
▼ Tank(s) Pumped □ Sjudge and scum measured.		Liquid Level of Tank in. Sludge Level in Scum Level in.			
1. Access used to	remove septage: Maintena	nce Hole 🔲 Other (G	io to #3 below)	* Tank must be pumped if is greater than 25%.	this value
2. If maintenance	hole was used, were all covers s	ecurely replaced? 🗶	Yes 🔲 No please expl e	ain	
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
١,	(ow	ner's name), refuse to a	allow the removal of solid	ls and liquids through the mai	intenance
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank desi	gned as a leaky tank? <i>example: s</i>	eepage pit, cesspool, dr	ywell, leaching pit		
Tank#1 🗌 Ye	s XNo Verificatio Method U	Jsed:			
Tank#2 🔲 Ye	s Verificatio Method l	Jsed:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	Yes No	Yes No	Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes TNo	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
	Pump Tank	☐ Yes No	☐ Yes No	☐ Yes ☐¶o	
6. How many ga	llons of septage were remove	d?			
Tank #1 /00	Tank #2 / 000	Pretreatment Ta	nk Pi	ump Tank / 000	
7. Other informa	ation: List any troubleshooting	g, minor repairs cond	ucted, tank safety conc	erns, or other concerns.	
8. Certification:	I hereby certify as a State of Mi and made the observations, or	directly supervised oth	ners in the performance o	of this job.	
Maintainer's N	ame: Hassle Free Septic	Maintaine 	er's Address: P.O. Box 702	North Branch, MN 55056	
Maintainer's Li	icense #: L3287 Maintair	ner's Phone #: 763-22	2-4397	7-21-11	
Maintainer's S	ignature M/Z		Date: /	7/1/6	ı