

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## **Subsurface Sewage Treatment System Maintenance Permit**

	completed in its entirety				
<u>prior</u> to perfor	ming maintenance activiti	es and remain on-	site for the durati	on of the maintenan	ce activity.
Date of Maintenance:	11-72-16 Reason	for Maintenance: _	Routine		·
Property Address:	5310 May Ave N ator zip: 5508	Р	roperty Owner's Na	ame: Cheryl.	Jurioi
Municipality: 517114	ater zip: 5508	<u> Property Ider</u>	ntification Number:		
	o: <u>k:3873.55416</u> N				
Maintena	nce Performed	Tank Meas	urement (must be	completed If tanks N	IOT pumped)
€ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see 3. Is there evidence of	nove septage: 🏻 Maintenar curely replaced? 🖾 Yes l of tank leakage from a sep aged, cracked, or structura	☐ No tic, holding, pretr	eatment or pump	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🗹 No	☐ Yes 🏿 No	☐ Yes ₩No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
	of septage were removed gal Tank #2		t tankg	al Pump Tank	gal
Tank #1 <i>1500</i>		_gal Pretreatmen			<del></del>
Tank #1 <i>1500</i>	gal Tank #2	_gal Pretreatmen			<del></del>
Tank #1 <i>1500</i>	gal Tank #2: List any troubleshooting	_gal Pretreatmen			<del></del>