



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit n	nust be completed
<u>prior</u> to perfo	rming maintenance activiti	es and remain on	-site for the durati	on of the maintenar	ice activity.
Date of Maintenance:	8/2/1C Reason	for Maintenance: _	Resource		
Property Address:	6722 ODELL	F	Property Owner's N	ame: MURK	
Municipality: \(\)\[\)\[\)\[\]	JMARIC ZIP:	Property Ide	ntification Number:		
Maintenance Permit N	10: 2 1428 KC932 N	Naintainer Name ar	nd License No	2989	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers se Is there evidence 	move septage: Maintenar ecurely replaced? Myes of of tank leakage from a sep aged, cracked, or structura	□ No tic, holding, preti	eatment or pump	tank below the oper	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🄀 No	☐ Yes No	☐ Yes \\No	
	Septic/Holding Tank #2	☐ Yes ☒No	☐ Yes 🏿 No	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000	gal Tank #2 (600)	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	n: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.